





This micrograph shows the interface between the epoxy resin and the carbon fiber fabric. The carbon fiber fabric is visible as a dark, textured layer, and the epoxy resin is the lighter, smoother material surrounding it. The interface appears to be well-bonded, with no visible gaps or delamination.







